

COPY

Idaho Department of Land

SUNDRY NOTICES AND REPORTS ON WELLS

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Well Permit Number LU-600045
2. Name of Operator Alta Mesa Services, LP		6. If Indian, Allottee or Tribe Name N/A
3a. Address 15021 Katy Freeway, Suite 400, Houston, TX 77094	3b. Phone No. (include area code) 281-530-0991	7. If Unit or CA/Agreement, Name and/or No. N/A
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 515 T8N R4W, 1560' FNL 2278' FEL		8. Well Name and No. DJS Properties @1-15
		9. API Well No. 11-075-20-020
		10. Field and Pool, or Exploratory Area Hamilton
		11. County or Parrish, State Payette, Idaho

CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> New Construction	<input type="checkbox"/> Stimulation Treat
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
	<input type="checkbox"/> Deepen	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <u>Slickline survey - pressure / PBTD</u>

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones, attach the Bond under which the work will be performed or provide the Bond No. on file with IDL. Required subsequent reports shall be filed within 30 days following completion of the involved operations. Final Abandonment Notices shall be filed only after operations. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Notify community within 1 mile of planned wellhead work; move in slickline wireline unit with a crane and set electronic memory pressure gauges in the well. Move out the slickline unit and move in well flow testing equipment. Flow test the well for three (3) days. Flare the natural gas and collect the condensate and water in portable tanks. Move out all well testing equipment and properly dispose of the produced water. Sell or dispose of the produced condensate. Leave the well shut in with gauges in the well. Move in a slickline wireline unit with a crane and retrieve the electronic memory pressure gauges from the well after the test has been completed. Move out the slickline unit.

14. I hereby certify that the foregoing is true and correct	
Name (Printed/Typed) Dale R. Hayes	Title Vice President - Operations
Signature <i>Dale R. Hayes</i>	Date 12/3/2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by <i>Steve T. Taylor</i>	Date 12/7/12
Title Area Manager	Office Southwest

*Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

RECEIVED

DEC 06 2012

Idaho L
SV